



UK

User Information (Professional boots marked with CE only)

- Always inspect boots before use. DO NOT use damaged boots.
- Keep soles clean as it will contribute to a long useful life of your boots.
- Clean boots after use with a brush and mild detergent.
- Store boots dry at 15-25°C.
- In the long term chemicals and high temperatures (above 60°C) may damage your boots.
- For any additional information contact the national sales office.

These boots comply with the PPE Regulation 2016/425, Category I.

EU Declarations of Conformity are available on the following link: www.dunlopboots.com/declarations

UA

Інформація для користувача (Для професійних черевиків із позначкою CE окрема інструкція)

- Завжди перевіряйте черевики перед використанням. НЕ використовуйте пошкоджені черевики.
- Тримайте підошви чистими, оскільки це сприятиме тривалому терміну служби ваших черевиків.
- Чистіть черевики після використання щіткою з м'яким миючим засобом.
- Зберігайте взуття в сухому стані при 15-25°C.
- У довгостроковій перспективі хімікати та високі температури (понад 60°C) можуть пошкодити ваші черевики.
- Для будь-якої додаткової інформації звертайтеся до національного офісу продажу.

Ці черевики відповідають Регламенту ЗІЗ 2016/425, категорія I.

Декларації відповідності ЄС доступні за таким посиланням: www.dunlopboots.com/declarations

Декларації відповідності UA доступні за таким посиланням: www.wimpel.com.ua/declarations